

GEOTECHNICAL ASSESSMENT

Slope Stability

29. The attached **Figure 1** and **Figure 2** show that all proposed house sites (building platform areas) have adequate setback distances apart from house sites 14, 15, ~~and~~ 16 ~~and~~ 21. The Structure Plan allows these ~~three~~ four sites to be moved if required once further geotechnical investigations are carried out at the subdivision scheme plan stage.